Diocese of Leicester: Register of Cases since 1 January 2000: Ab Kettleby - Aylestone

| Ben No: | Church | | |
|-------------|---|---|--|
| 10202 | Ab Kettleby, St James the Greater | | |
| Case No: | L142/2007 | Informal ☐ Minor Works Fabric ☐ | |
| Creation of | a Garden of Remembrance to the east of the Church Lane entrance to the churchyard | Minor Works Trees ☐ Faculty ☑ | |
| | | Recommended Not Recommended No objections | |
| | | | |
| | | Withdrawn | |
| | | Faculty Issued? | |
| DAC Certi | ificate Conditions: - | Date Faculty Issued 21/02/2008 | |

- 1. A time limit of 12 months
- 2. That the PCC complies with any conditions of the granting of planning permission 3. That the specification for the plaques should read "brass and up to a maximum of 6" by 3"

Page 1 of 139

| Case No: L082/2007 | Informal 🗀 Minor Works Fabric 🗀 |
|---|---|
| 1. Removal of 6 trees 2. Lift lower limbs of Cedar tree 3. Reduced limes tree by 25% | Minor Works Trees Faculty □ Recommended Not Recommended No objections |
| 3. Reduce Lime tree by 25% | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| Case No: L053/2008 | Informal ☐ Minor Works Fabric ☑ |
| Investigation works required by English Heritage as part of repair grant development stage (as set out email to Ray Anderton of 27 February 2008) | Minor Works Trees ☐ Faculty ☐ |
| email to May Amacron of 27 February 2000) | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That the DAC Archaeological Adviser is consulted priort to the radar scans and any disturbance of the ground | |
| | |

29 February 2024 Page 2 of 139

| Case No: L073/2008 | Informal 🗀 Minor Works Fabric 💆 |
|--|---|
| Emergency minor repairs to spire on the grounds of safety agreed with Michael Goodhart: - 1. Removal of the weathervane for safe-keeping 2. Earthing of the bell-frame and completion of the lightning conductor path 3. Replacement of 2 iron cramps on the south side of the spire 4. Replacement of the access door from the spire to the tower walkway | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That the works are recorded in the Log Book so that a record is kept of what has been done | |
| Case No: L076/2011 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| To cut back overhanging branches | Minor Works Trees |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done. | |

29 February 2024 Page 3 of 139

| Case No: L121/2011 | Informal 🗀 Minor Works Fabric 🗀 |
|--|---|
| Repairs to roof following lead theft | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? \square |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L135/2011 | Informal □ Minor Works Fabric □ |
| Investigation works into the cause of the damage which has temporarily (3 years) closed the church | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 12/07/2011 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 4 of 139

| Case No: L116/2012 | Informal $\ \ \Box$ Minor Works Fabric $\ \ \Box$ |
|--|---|
| Repairs to the: - 1. Nave | Minor Works Trees ☐ Faculty ✓ |
| 2. Chancel | Recommended Not Recommended No objections |
| 3. North Aisle | |
| 4. South Aisle | |
| 5. South Porch | Mrs. I |
| 6. Tower and Spire | Withdrawn |
| as per the Engineer's Report, Architect's Specification and drawings | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 30/07/2012 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 3. That no works shall take place until the PCC, after consultation with the Diocesan | |
| Case No: L098/2012 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Works to trees comprising (numbers as per the plan by Rodney Helliwell): - 1. Fell: - | Minor Works Trees ✓ Faculty □ |
| a) no. 2 | Recommended Not Recommended No objections |
| b) no. 3 | |
| 2. Prune: - | |
| a) no. 1 | Withdrawn |
| b) no. 5 | Withdrawn |
| 3. Reduce height of: - | Faculty Issued? □ |
| a) no. 6 | Faculty issued? |
| b) no.7 | |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Wilat has been done | |

29 February 2024 Page 5 of 139

| Case No: L183a/2013 | Informal 🗀 Minor Works Fabric 🗀 |
|--|--|
| Refurbishment of the current Bell installation Installation of 3 additional bells | Minor Works Trees ☐ Faculty ✔ Recommended Not Recommended No objections ✔ ☐ ☐ |
| | Withdrawn ☐ Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 04/03/2015 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L183/2013 | Informal ☑ Minor Works Fabric ☐ |
| Installation of: - 1. Accessible WC in the base of the Tower 2. Trench-arch Drainage System in the churchyard 3. Servery at the west end of the South Aisle | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 6 of 139

| Case No: L218/2014 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| Removal of existing overhead power supply Installation of new underground power supply | Minor Works Trees ☐ Faculty ☑ |
| 2. Installation of new underground power supply | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 22/12/2014 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 2. That no works shall take place until the PCC, after consultation with the Diocesan | |
| Archaeological Adviser, has secured the implementation of a programme of | |
| Case No: L181/2015 | Informal ☐ Minor Works Fabric ☑ |
| Installation of: - | Minor Works Trees \Box Faculty \Box |
| 1. 24 x under-Pew Heaters2. 12 x double-pole switches | Recommended Not Recommended No objections |
| 3. 1 x triple pole and neutral distribution board | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| 2. That details of the works are entered in the Log Book so that a record is kept of | |
| what has been done 3. That, in line with the requirement and advice of the Ecclesiastical Insurance Group, | |
| o. That, it is to requirement and advise of the Ecologiacidal medianice Gloup, | |

29 February 2024 Page 7 of 139

| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| CONFIRMATORY APPLICATION for works undertaken with Interim Faculty: - | Minor Works Trees ☐ Faculty ✓ |
| Replacement of South Aisle roof covering | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued 10/12/2019 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric ☑ |
| Installation of Temporary Burglar Alarm | Minor Works Trees |
| | Recommended Not Recommended No objection |
| | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| That the PCC considers the installation of a permanent roof alarm and makes a separate detailed application for this before the temporary alarm is removed | |

29 February 2024 Page 8 of 139

| Ben No: | Church | |
|----------------|-----------------------|--|
| 10303 | Allexton, St Peter | |
| Case No: | L089/2005 | Informal $\ \square$ Minor Works Fabric $\ ^{ullet}$ |
| 1. To fell a l | | Minor Works Trees ☐ Faculty ✓ |
| 2. To cut ba | ack IVy | Recommended Not Recommended No objections |
| | | |
| | | Withdrawn |
| | | Faculty Issued? |
| DAC Certi | ificate Conditions: - | Date Faculty Issued |
| 1. A time lin | mit of 12 months | |
| | | |
| | | |

29 February 2024 Page 9 of 139

| Case No: L103/2015 | Informal 🗀 Minor Works Fabric 💆 |
|--|--|
| Removal of: - 1. Major deadwood from all trees in the churchyard 2. Large limb from Lime Tree | Minor Works Trees Faculty Recommended Not Recommended No objections |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal \Box Minor Works Fabric \Box |
| Creation of Garden of Remembrance | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? 🗹 |
| DAC Certificate Conditions: - | Date Faculty Issued 20/07/2018 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 10 of 139

| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ | |
|--|---|------------|
| Introduction of a memorial for Jean Jessop | Minor Works Trees Faculty | ✓ |
| | Recommended Not Recommended No | objections |
| | | |
| | Withdrawn | |
| | Faculty Issued? ✓ | |
| DAC Certificate Conditions: - | Date Faculty Issued 13/03 | /2022 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | | |

29 February 2024 Page 11 of 139

| Ben No: | Church | |
|--|----------------------|---|
| 20501 | Anstey, St Mary | |
| Case No: | L145/2001 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Removal of defective plaster in Chancel and re-plastering of the area in accordance with approved quotation prepared by Brian E Head Re-decoration of Chancel using micro-porous paint in accordance with approved quotation prepared by Steve Bosch | | Minor Works Trees ☐ Faculty ✓ |
| | | Recommended Not Recommended No objections |
| | | Withdrawn |
| | | Faculty Issued? |
| DAC Certi | ficate Conditions: - | Date Faculty Issued |
| 1. A time lin | nit of 12 months | |

29 February 2024 Page 12 of 139

| Case No: L086/2003 | Informal $\;\sqcup\;$ Minor Works F | abric \square |
|--|-------------------------------------|---------------------|
| Urgent repairs to the north wall pinnacle, which is in a dangerous state likely to become a public danger if high winds are experienced in the winter, in accordance with the approved quotation prepared by | Minor Works Trees $\ \Box$ | Faculty 🗹 |
| Midland Stone Masonry | Recommended Not Recomm | ended No objections |
| | | |
| | Withdrawn [| |
| | Faculty Issued? \Box | |
| DAC Certificate Conditions: - | Date Faculty Issued | |
| A time limit of 12 months 2. That the work should be carried out under the direction of the architect | | |
| Case No: L054/2004 | Informal Minor Works F | abric \Box |
| To take down and remove old church Noticeboard | Minor Works Trees | Faculty 🗹 |
| 2. Provide and fix new noticeboard as per detailed drawing supplied by NIS Signs dated 15 March 2004 | Recommended Not Recomm | ended No objections |
| | | |
| | Withdrawn [| |
| | Faculty Issued? 🗹 | |
| DAC Certificate Conditions: - | Date Faculty Issued | 09/08/2004 |
| A time limit of 12 months 2. PCC needs to check with the Chaplain to the Deaf Centre the most appropriate logo/wording | | |
| | | |

29 February 2024 Page 13 of 139

| Case No: L141/2007 | Informal 🗀 Minor Works Fabric 🗀 |
|--|---|
| Installation of projector screen behind the Chancel arch | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 03/06/2008 |
| A time limit of 12 months That, where possible, all fixings should be made into joints, not stonework, using stainless steel or non-ferrous screws in fibre plugs That all wiring should be as unobtrusive as possible and of an appropriate colour to | |
| Case No: L061/2008 | Informal ☐ Minor Works Fabric ☐ |
| Restoration of the Organ | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 16/09/2008 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 14 of 139

| Case No: L120/2008 | Informal 🗀 Minor Works Fabric 🗀 |
|--|---|
| Private Faculty Application: - | Minor Works Trees ☐ Faculty 🗹 |
| Installation of drain in plum slate adjacent to boundary between churchyard and 51 Bradgate Road | Recommended Not Recommended No objections |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That that the trench should be: - | |
| Case No: L172/2010 | Informal □ Minor Works Fabric □ |
| Following the 2006 QI Report, repairs to pinnacles and stonework | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? 🗹 |
| DAC Certificate Conditions: - | Date Faculty Issued 07/12/2010 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 15 of 139

| Case No: L020/2010 | Informal 🗹 Minor Works Fabric 🗌 |
|--|--|
| CONFIRMATORY APPLICATION: - | Minor Works Trees ☐ Faculty ✓ |
| Repair to window in the Lady Chapel | Recommended Not Recommended No objections □ □ □ ✓ |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 13/04/2011 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L149/2013 | Informal □ Minor Works Fabric ☑ |
| 1. Re-wiring of the interior of the Church following existing routes in present conduit | Minor Works Trees Faculty |
| 2. Replacement of the existing conventional spot lights with LED spot lights | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| 2. That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| That the existing conduit should be re-used and, assuming that it is metal, any | |

29 February 2024 Page 16 of 139

| Case No: L086/2013 | Informal 🗹 Minor Works Fabric 🗆 |
|--|---|
| 1. Construction of extension to accommodate accessible WC | Minor Works Trees \Box Faculty \Box |
| 2. Re-ordering Scheme comprising: - a) Adaptation of Vestries to incorporate a Servery | Recommended Not Recommended No objections |
| b) Removal of pews: - i) in the North Aisle | |
| ii) West of the middle pillar to both of the Nave c) Replacement of pew platforms with new stone floor | Withdrawn |
| d) Re-configuring of existing Vestries to incorporate Servery e) Introduction of stackable chairs | Faculty Issued? □ |
| f) Renewal of heating system including new boiler, heating pipes & radiators and rerasbestos from the boiler house | noval of |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| Repairs to churchyard wall | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 2. That the Conservation Officer approves a sample of the mortar mix and a sample panel of re-pointing | |

29 February 2024 Page 17 of 139

| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| Re-ordering Scheme comprising: - 1. Adaptation of Vestries to incorporate a Servery 2. Removal of pews: - a) in the North Aisle b) West of the middle pillar to both of the Nave 3. Replacement of pew platforms with new stone floor 4. Re-configuring of existing Vestries to incorporate Servery 5. Introduction of stackable chairs 6. Renewal of heating system including new boiler, heating pipes & radiators and removal of asbestos from the boiler house | Minor Works Trees ☐ Faculty ☐ Recommended Not Recommended No objections ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric □ |
| Replacement and Renewal of broken and obsolete heating boiler and system | Minor Works Trees Faculty Recommended Not Recommended No objections ✓ □ □ Withdrawn □ Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 04/06/2021 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That, noting how the asbestos lagging was applied in the boiler chamber, the heating contractor should be cautious when stripping out any buried pipework in the | |

29 February 2024 Page 18 of 139

| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|---|--|
| Removal of Pews from: - a) North Aisle b) West end c) South Aisle Installation of accessible WC and Servery Replacement of pew platforms with new stone floor Introduction of stackable chairs Possible replacement of existing internal lobby and storage area in South Aisle Creation of additional storage Possible re-location/adpation of the Font Compeletion of renewed heating system | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| Repairs to a pinnacle | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That the original pinnacle must be kept as a template. | |

29 February 2024 Page 19 of 139

| Ben No: | Church | |
|-------------------------------|--|---|
| 20206 | Appleby Magna, St Michael and All Angels | |
| Case No: | L117/2000 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Re-wiring and electrical work | | Minor Works Trees ☐ Faculty ✓ |
| | | Recommended Not Recommended No objections |
| | | |
| | | Withdrawn |
| | | Faculty Issued? ✓ |
| DAC Cert | ificate Conditions: - | Date Faculty Issued 27/04/2001 |
| 1. A time lir | mit of 12 months | |

29 February 2024 Page 20 of 139

| Case No: L010/2000 | Informal $\ \ \Box$ Minor Works Fabric $\ \ \Box$ |
|---|---|
| New internal doors and memorial plaque | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 22/12/2000 |
| A time limit of 12 months 2. That the doors should be constructed in American Oak stained to match the existing internal timberwork | |
| Case No: L031/2001 | Informal ☐ Minor Works Fabric ☐ |
| 1. Repairs to Chancel floor | Minor Works Trees ☐ Faculty ☑ |
| 2. Repairs to plasterwork | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| | |
| | |

29 February 2024 Page 21 of 139

| Case No: L083/2003 | Informal $\;\square\;$ Minor Works Fabric $\;\square\;$ |
|--|---|
| Glazing repairs together with associated stonework repairs Re-plastering work | Minor Works Trees ☐ Faculty ✓ |
| 2. Re-plastering work | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 10/03/2004 |
| A time limit of 12 months 2. That all work should be carried out under the direction of the Church Architect | |
| Case No: L172/2008 | Informal □ Minor Works Fabric □ |
| CONFIRMATORY FACULTY for works undertaken with Chancellor's Consent: - | Minor Works Trees ☐ Faculty ☑ |
| 1. Repairs to roof ridge capping of: - a) Nave | Recommended Not Recommended No objections |
| b) North Aisle c) Chancel | |
| Application of "Smartwater" (Minor Works item) | Withdrawn |
| | Faculty Issued? <a> ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 28/01/2009 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 22 of 139

| Case No: L140/2009 | Informal 🖂 Minor Works Fabric 🗀 |
|--|---|
| Replacement of Safe | Minor Works Trees ☐ Faculty 🗹 |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? 🗹 |
| DAC Certificate Conditions: - | Date Faculty Issued 16/09/2009 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L129/2009 | Informal ☐ Minor Works Fabric ☑ |
| CONFIRMATORY APPLICATION: - | Minor Works Trees ☐ Faculty ☐ |
| Installation of new locks to: - 1. Cellar door | Recommended Not Recommended No objections |
| 2. Porch door | |
| 3. Tower door4. Vestry door5. Chancel door | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 23 of 139

| Case No: L003/2010 | Informal $\ \square$ Minor Works Fabric $\ \square$ | |
|--|---|--|
| Re-building of 5 metre section of churchyard wall | Minor Works Trees ☐ Faculty ✓ | |
| | Recommended Not Recommended No objections | |
| | | |
| | Withdrawn | |
| | Faculty Issued? ✓ | |
| DAC Certificate Conditions: - | Date Faculty Issued 23/03/2010 | |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | | |
| Case No: L050/2011 | Informal $\ \square$ Minor Works Fabric $\ \square$ | |
| To open up for investigation and inspection: - | Minor Works Trees ☐ Faculty ☑ | |
| a) South Aisle roof b) South valley gutter | Recommended Not Recommended No objections | |
| c) East gable abutments d) Removal of Weathervane | | |
| prior to remedial application (separate application to follow) | Withdrawn | |
| | Faculty Issued? ✓ | |
| DAC Certificate Conditions: - | Date Faculty Issued 23/06/2011 | |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | | |

29 February 2024 Page 24 of 139

| Case No: L002/2011 |
|--|
| 1. Disposal of existing Green Altar Frontal |
| 2. Introduction of 4 seasonal Altar Frontals formerly at Glenfield, St Peter |
| |
| |
| |

DAC Certificate Conditions: -

- 1. A time limit of 12 months
- 2. That details of the works are entered in the Log Book so that a record is kept of what has been done

| Informal \square Mino | r Works Fabric | ✓ |
|-------------------------|-----------------|---------------|
| Minor Works Trees | s | lty \square |
| Recommended No | t Recommended | No objections |
| ✓ | | |
| With | drawn 🗌 | |
| Faculty Is | sued? \square | |
| Date Faculty Iss | ued | |

29 February 2024 Page 25 of 139

Case No: L109/2011

Works to the following 9 trees: -

- 1. Tree 01 Thorn species dying straight fell
- 2. Tree 12 Hawthorn sever lvy
- 3. Tree 14 Large-leaved lime remove basal growth
- 4. Tree 17 Common Lime clean out, general works, sever ivy, minor dead wood, extensive areas of internal trunk decay requiring crown reduction no greater than 25%
- 5. Tree 18 Horse Chestnut clean out, general works, broken hanging branches, extensive areas of internal trunk decay requiring crown reduction no greater than 30%
- 6. Tree 19 Common Lime sever ivy
- 7. Tree 34 Giant Redwood clean out, general works, minor deadwood < 100mm
- 8. Tree 36 English Oak clean out, general works, broken hanging branches, major deadwood > 100mm
- 9. Tree 42 Blue Atlas Cedar clean out, general works, minor deadwood < 100m

DAC Certificate Conditions: -

- 1. A time limit of 12 months
- 2. That details of the works are entered in the Log Book so that a record is kept of what has been done

| Informal $\ \square$ Minor Works Fabric $\ \square$ | | | |
|---|-----------|--------|---------------|
| Minor Works T | rees | Facul | lty \square |
| Recommended | Not Recom | mended | No objections |
| \checkmark | | | |
| Withdrawn | | | |
| Faculty Issued? \square | | | |

Date Faculty Issued

29 February 2024 Page 26 of 139

| Case No: L046/2011 | Informal 🗀 Minor Works Fabric 💆 |
|---|---|
| Removal and repair of leaded light | Minor Works Trees |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That the PCC asks the contractor to check the other tracery lights for weak lead | |
| Case No: L172/2012 | Informal ☐ Minor Works Fabric ☑ |
| Installation of a Bench in the churchyard in memory of Cyril Reading | Minor Works Trees ☐ Faculty ☐ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 27 of 139

| Case No: L014/2012 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| Repair works to Tower and Spire following 2010 QI Report and English Heritage Survey Report and investigations | Minor Works Trees ☐ Faculty ✓ |
| in reedigations | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 14/03/2012 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L177/2013 | Informal □ Minor Works Fabric ☑ |
| Installation of new Sound and Induction Loop System | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| 2. That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 3. That the PCC ensures the contractor complies with the DAC Conditions on the | |

29 February 2024 Page 28 of 139

| Case No: L164/2015 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|---|---|
| 1. (2.1) Re-location of flat headstones where arranged next to church in 1960 to elsewhere churchyard | e in the Minor Works Trees Faculty |
| (2.2) Removal of concrete channels and bases surrounding the Chancel / Chapel (4) Renewal / Creation of French-type Land Drains | Recommended Not Recommended No objections |
| 4. (5) Add, upgrade & refurbish Rainwater Goods; treat with Smartwater & anti-climb paint 5. (3) New below-ground gulleys, pipes and soakaways | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 08/12/2015 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 2. That the PCC causes the enclosed advertisement to be published on the Diocesan website and submits to the Diocesan Registrar a copy of the Advertisement as it was | |
| Case No: L025/2015 | Informal ☐ Minor Works Fabric ☐ |
| 1. In the closed churchyard: - | Minor Works Trees ✓ Faculty □ |
| a) Tree 19 Common Lime (clean out & general works) b) Tree 57 Hawthorn (cut Ivy & general works) | Recommended Not Recommended No objections |
| In the open Churchyard: - a) Tree 34 Giant Redwood (clean out & general works) | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 29 of 139

| Case No: L086/2015 | Informal 🗌 Minor Works Fabric 🗹 |
|---|---|
| Low level mortar repairs | Minor Works Trees |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That the work should be carried out at the direction of the church architect | |
| Case No: | Informal □ Minor Works Fabric □ |
| 1. Clock chamber ceiling & Clock repairs | Minor Works Trees ☐ Faculty ✔ |
| Installation of automatic winding | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 24/10/2016 |
| That details of the works are entered in the Log Book so that a record is kept of | |
| what has been done 2. That the Clock must be securely protected from the ingress of dust when the debris | |
| from above is being removed | |

29 February 2024 Page 30 of 139

| Case No: | Informal 🗀 Minor Works Fabric 💆 |
|--|---|
| Pollarding of Lime Tree - number 26 | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric ☑ |
| Replacement of South Aisle roof covering | Minor Works Trees ☐ Faculty ☐ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 31 of 139

| Case No: | Informal 🗀 Minor Works Fabric 🗹 |
|--|---|
| Replace roof following theft | Minor Works Trees \Box Faculty \Box |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric ☑ |
| Repairs to Vestry lock | Minor Works Trees ☐ Faculty ☐ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 32 of 139

| Case No: | Informal 🗀 Minor Works Fabric 🗀 |
|--|---|
| Repairs to the Pipe Organ | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 18/06/2019 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Repairs to the Mould monument in the Chancel | Minor Works Trees ☐ Faculty ☑ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 19/07/2019 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 33 of 139

| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| Installation of demountable handrail for step Nave/Chancel | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 19/07/2019 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 2. That the design of the handrail must match that the Communion Rails | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| Replacement of Safe | Minor Works Trees ☐ Faculty ☐ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 34 of 139

| Case No: | Informal 🗀 Minor Works Fabric 💆 |
|--|---|
| Work to Trees 17,19,57, 21, 36, 45, 47, 49, 54, 56 | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric ☑ |
| Repairs to Chancel: - | Minor Works Trees \Box Faculty \Box |
| South pew Floor | Recommended Not Recommended No objections |
| 3. Panelling | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 35 of 139

| Case No: | Informal 🗌 Minor Works Fabric 🗹 |
|---|---|
| Repair & re-securing of upper Spirelight birdguard | Minor Works Trees \Box Faculty \Box |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| That, where possible, all fixings should be made into joints, not stonework, using stainless steel or non-ferrous screws in fibre plugs | |
| Case No: | Informal □ Minor Works Fabric □ |
| Local variation of the Churchyard Regulations | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 36 of 139

| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|---|---|
| Restoration 2 Chancel south windows | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 16/11/2020 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 2. That any stone that is to be replaced should be checked for signs of re-use, masons' marks, graffiti etc. and if found contact the Diocesan Archaeological Advisor | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| Repair bell wheel | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 37 of 139

| Ben No: | Church | |
|--|-----------------------|---|
| 20301 | Arnesby, St Peter | |
| Case No: | | Informal ☐ Minor Works Fabric ☐ |
| No Faculty / Informal Advice / Minor Works application has been made | | Minor Works Trees ☐ Faculty ☐ |
| | | Recommended Not Recommended No objections |
| | | |
| | | Withdrawn |
| | | Faculty Issued? |
| DAC Cert | ificate Conditions: - | Date Faculty Issued |
| 1. A time lir | mit of 12 months | |

29 February 2024 Page 38 of 139

| Case No: L/1995 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| Re-decoration | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| Case No: L/1999 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Installation of elevated floor for ringing chamber | Minor Works Trees ☐ Faculty ☑ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn ✓ |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| | |

29 February 2024 Page 39 of 139

| Case No: L150/2001 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|---|---|
| General repairs using matching materials to stonework of main walls and tower, roofs and windows | |
| as detailed in the approved specification of Corporate Archiecture Ltd dated September 2000 revis B herewith | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| Case No: L169/2006 | Informal □ Minor Works Fabric □ |
| New Lighting Scheme | Minor Works Trees ☐ Faculty ✔ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 08/01/2007 |
| 1. A time limit of 12 months | |
| 2. That all wiring should be as unobtrusive as possible and of an appropriate colour to blend with the background | |
| 3. That, where possible, all fixings should be made into joints, not stonework, using | |

29 February 2024 Page 40 of 139

| Case No: L080/2007 | Informal 🗹 Minor Works Fabric 🗌 |
|---|---|
| Within the Tower, installation of: - a) WC for the disabled with trench arch drainage system in the churchyard b) Mezzanine ringing chamber At the west end of the South Aisle, construction of of servery Installation of water supply across the churchyard | Minor Works Trees ☐ Faculty ✔ Recommended Not Recommended No objections ✔ ☐ ☐ Withdrawn ☐ |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 15/07/2009 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That no works shall take place until the PCC, after consultation with the Diocesan | |
| Case No: L010/2011 | Informal □ Minor Works Fabric □ |
| Minor roof Major stonework repairs | Minor Works Trees ☐ Faculty ✔ Recommended Not Recommended No objections ✔ ☐ ☐ Withdrawn ☐ Faculty Issued? ✔ |
| DAC Certificate Conditions: - | Date Faculty Issued 25/03/2011 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | 20/03/2011 |

29 February 2024 Page 41 of 139

| Case No: L009/2011 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| Replacement of existing gas boiler | Minor Works Trees ☐ Faculty ✔ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 04/03/2011 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That the contractor should confirm that the gas installation and boiler ventilation | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| External stonework repairs to the doorway | Minor Works Trees ☐ Faculty ☐ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That any stonework to be replaced is carefully checked for tool marks and, if found, | |
| the stones are set aside and Diocesan Archaeological Adviser is notified | |

29 February 2024 Page 42 of 139

| Case No: | Informal $\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$ |
|--|--|
| CONFIRMATORY APPLICATION for works unertaken with Interim Faculty: | Minor Works Trees ☐ Faculty ✓ |
| Re-covering of the South Aisle roof | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 09/05/2019 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric □ |
| Fell 1 dead tree | Minor Works Trees |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 43 of 139

| Case | No: |
|------|-----|
|------|-----|

| 1. Pollard 4 trees | | |
|----------------------------|--|--|
| 2. Reduce canopy of 1 tree | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

DAC Certificate Conditions: -

- 1. That details of the works are entered in the Log Book so that a record is kept of what has been done
- 2. That the PCC be aware of the possibility of there being bat roosts in mature trees it would be god practice to scan the area with a bat detector prior to work commencing

| Informal \square M | inor Works Fa | abric 🗆 | |
|----------------------|---------------|---------|------------|
| Minor Works Tr | ees 🗸 | Faculty | |
| Recommended | Not Recomme | nded No | objections |
| ✓ | | | |
| V | Vithdrawn |] | |
| Faculty | / Issued? | | |
| Date Faculty | Issued | | |

29 February 2024 Page 44 of 139

| Ben No: | Church | |
|---|-----------------------|---|
| 10202 | Asfordby, All Saints | |
| Case No: | L/1999 | Informal \square Minor Works Fabric \square |
| Installation | | Minor Works Trees ☐ Faculty ✓ |
| Disabled Sink unit | | Recommended Not Recommended No objections |
| | | |
| | | Withdrawn |
| | | Faculty Issued? ✓ |
| DAC Certi | ificate Conditions: - | Date Faculty Issued 08/05/2000 |
| 1. A time lir | mit of 12 months | |

29 February 2024 Page 45 of 139

| Case No: L138/2000 | Informal 🗀 Minor Works Fabric 🗀 |
|--|---|
| Installation of a new heating system including re-location of boilers all in accordance with the approved specification of Pick Everard dated 14 November 2000 and drawings and illustrations all herewith | Minor Works Trees ☐ Faculty ☑ Recommended Not Recommended No objections ☐ ☐ ☐ |
| | Withdrawn ☐ Faculty Issued? ☐ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| Case No: L011/2000 | Informal ☐ Minor Works Fabric ☐ |
| Installation of Sound Reinforcement and Loop System in accordance with the approved specification of French Electrical Services dated 15 October 1999 Replacement boiler | Minor Works Trees ☐ Faculty ☐ Recommended Not Recommended No objections ☐ ☐ Withdrawn ☐ |
| | Withdrawn [_] |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 05/05/2001 |
| A time limit of 12 months 2. That all wiring shall colour match the background stonework | |

29 February 2024 Page 46 of 139

| Case No: L013/2004 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| 1. Works to spire: - | Minor Works Trees ☐ Faculty ✓ |
| a) Tie-bar/weathervane - erect ladders internally, inspect tie-bar/base plate, erect scaffold around top 5 metres, secure capstone | Recommended Not Recommended No objections |
| b) Spire pointing - rake back suspect joints, point with lime gauge mortar | |
| c) Tie-bar base plate - if inspection indicates necessity, remove and replace | |
| 2 Spire lunettes - install stainless-steel mesh, check timbers | Withdrawn |
| 3 Tower louvres - treat timbers with wood preservative 4 Tower pinnacles - prepare and point open joints, secure stonework | |
| 5 Vegetation - remove from tower floor and lead gully, trewat roots, seal open joints | Faculty Issued? <a>✓ |
| 6 Tower floor - investigate lead gully and report | |
| DAC Certificate Conditions: - | Data Faculty lagued |
| | Date Faculty Issued 09/03/2004 |
| 1. A time limit of 12 months | |
| Case No: L148/2005 | Informal ☐ Minor Works Fabric ☐ |
| Alterations to access to South Porch involving: - | Minor Works Trees ☐ Faculty ☑ |
| 1. Re-location of 2 headstones to extend flagged area outside the porch | Recommended Not Recommended No objections |
| Re-grade & re-surface path Lower threshold between porch and nave | • |
| 4. Install new ramp | |
| All set out in the proposals by M Goodhart (February 2005) | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 23/12/2005 |
| 1. A time limit of 12 months | |
| 2. That the headstones to be moved should be kept up-right | |
| 3. That the PCC makes every effort to ensure that the ramp is as compliant with the | |

29 February 2024 Page 47 of 139

Disability Discrimination Act Regulations as possible

| Case No: L104/2005 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|---|--|
| CONFIRMATORY FACULTY: - 1. Disconnect the faulty underground section of MICC cable, supplying the organ point, boiler and sump pump etc. | Minor Works Trees ☐ Faculty ☑ Recommended Not Recommended No objections |
| 2. Replace with a new MCCC cable with PVC cover to run from the mains position overhead along the beams and through the church with the existing MICC lighting supply cables and connected to the | |
| existing circuit points | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 02/11/2005 |
| A time limit of 12 months That all wiring should be as unobtrusive as possible and of an appropriate colour to blend with the background That, where possible, all fixings should be made into joints, not stonework, using | |
| Case No: L185/2006 | Informal ☐ Minor Works Fabric ☐ |
| Installation of window guards to 5 windows: - a) West window | Minor Works Trees ☐ Faculty ☑ |
| b) South Transept east wall & s wall (x 2) | Recommended Not Recommended No objections |
| c) Chancel south wall western window | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 09/01/2007 |
| 1. A time limit of 12 months | |
| 2. That the grills are of black powder coated stainless steel and shaped to fit into any tracery or the overall shape of the windows | |
| 3. That, where possible, all fixings should be made into joints, not stonework, using | |

29 February 2024 Page 48 of 139

| Case No: L019/2006 | Informal 🗹 Minor Works Fabric 🗀 |
|---|---|
| Re-ordering of the church to provide a Nave Altar on a carpeted timber-framed platform (to extend Chancel step) with de-mountable Communion Rails | Minor Works Trees ☐ Faculty ✓ |
| Onancer step) with de mountable communion rans | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 12/04/2007 |
| A time limit of 12 months That the dais be ventilated | |
| Case No: L115/2007 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| 1. Removal of limbs from a Beech tree & re-balancing of the crown | Minor Works Trees ✓ Faculty □ |
| 2. Removal of lower limbs from 2 Lime trees obstructing paths | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| | |
| | |
| | |

29 February 2024 Page 49 of 139

| Case No: L199/2007 | Informal 🗀 Minor Works Fabric 🗀 |
|--|---|
| To remove: - 1. Dead Llandi | Minor Works Trees ✓ Faculty □ |
| 2. Llandi entagled with two lime trees and consequently dying | Recommended Not Recommended No objections |
| 3. Self-seeded sapling growing near to old Rectory wall threatening the fabric of the wall which could render it unsafe | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| Case No: L196/2008 | Informal ☐ Minor Works Fabric ☐ |
| Restoration of the Organ comprising: - 1. Removal of electrical action to the swell and replacement with mechanical action | Minor Works Trees ☐ Faculty ☑ |
| Replacement of inoperative parts | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 09/01/2009 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 50 of 139

| Case No: L080/2008 | Informal 🗹 Minor Works Fabric 🗹 |
|---|---|
| Installation of new lighting for the Pulpit | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That where possible all finings should be read a jets in into a standard walls. | |
| 2. That, where possible, all fixings should be made into joints, not stonework, using stainless steel or non-ferrous screws in fibre plugs | |
| Case No: L058/2009 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Replacement of the existing wooden Porch gates with metal gates | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| 2. That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 3. That, where possible, all fixings should be made into joints, not stonework, using | |

29 February 2024 Page 51 of 139

| Case No: L222/2011 | Informal ☐ Minor Works Fabric ☑ |
|--|---|
| Installation of PIR security system to cover:- | Minor Works Trees \Box Faculty \Box |
| North Transept North Aisle | Recommended Not Recommended No objections |
| 3. South Transept | |
| 4. South/West Aisle | |
| 5. Porch | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 3. That, where possible, all fixings should be made into joints, not stonework, using | |
| Case No: L108/2011 | Informal ☐ Minor Works Fabric ☐ |
| Timber and roof works to the: - | Minor Works Trees ☐ Faculty ☑ |
| North Transept South Aisle | Recommended Not Recommended No objections |
| 3. Porch | |
| 4. South Transept | |
| 5. North Aisle | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 09/08/2011 |
| 1. A time limit of 12 months | |
| 2. That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 3. That terne-coated stainless steel (or other acceptable material) is used rather than | |

29 February 2024 Page 52 of 139

| Case No: L101/2011 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|--|
| Lifting the canopies of 12 x Lime Trees Trimming and shaping of 2 x Conifer Trees Cutting back of Privet hedges | Minor Works Trees |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L023/2013 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Disposal of 150 post-Victorian wooden chairs Introduction of 150 second-hand lightweight, stackable metal-framed chairs | Minor Works Trees ☐ Faculty ✔ Recommended Not Recommended No objections ✔ ☐ ☐ Withdrawn ☐ |
| | Faculty Issued? 🗹 |
| DAC Certificate Conditions: - | Date Faculty Issued 17/04/2013 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 53 of 139

| Case No: | Informal 🗌 Minor Works Fabric 🗹 |
|--|---|
| Works to Trees as set out in Report from Dalby Tree Care | Minor Works Trees |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| Work to trees in churchyard as set out in the Churchyard Tree Report dated 14th November 2017 | Minor Works Trees |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 54 of 139

| Ben No: | Church | _ |
|---|---|---|
| 10207 | Ashby Folville, St Mary | |
| Case No: | L042/2005 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| | 2 redundant radiators in the North and South Aisles | Minor Works Trees ☐ Faculty ✓ |
| Remove the remaining freestanding radiators around the church | Recommended Not Recommended No objections | |
| | | |
| | | Withdrawn |
| | | Faculty Issued? ✓ |
| DAC Certi | ificate Conditions: - | Date Faculty Issued 10/05/2005 |
| 1. A time lin | mit of 12 months | |
| | | |
| | | |

29 February 2024 Page 55 of 139

| Case No: L125/2010 | Informal 🗹 Minor Works Fabric 🗌 |
|---|---|
| Disposal of 2 x 48" Victorian oak candlesticks for wax candles Installation of 2 x 48" new oak candlesticks with 16" oil-filled candles in memory of Wing Commander John H Smith-Carington | Minor Works Trees Faculty Recommended Not Recommended No objection |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 29/09/2010 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That the tripod of legs design should be chosen | |
| Case No: L126/2010 | Informal ☑ Minor Works Fabric ☐ |
| Introduction of 16" x 11" engraved brass plaque with black lettering to commemorate the residency of | Minor Works Trees \Box Faculty \Box |
| the Polish community 1948 - 1966 in the parish | Recommended Not Recommended No objection |
| | |
| | Withdrawn |
| | ☐ Faculty Issued? ☑ |
| DAC Certificate Conditions: - | Date Faculty Issued 29/09/2010 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 3. That, where possible, all fixings should be made into joints, not stonework, using | |

29 February 2024 Page 56 of 139

| Case No: L091/2011 | Informal $\ igsqcup$ Minor Works Fabric $\ igsqcup$ |
|--|--|
| 1. To reduce 1 Ash by approx. 20% and shape accordingly – the tree is overgrown with branches and is quite misshapen 2. To cut down 1 Cypress which has grown very tall – about 60' – and sways in the winth the stained glass window behind the altar (c 15') | d. It is close to Recommended Not Recommended No objections |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L045/2011 | Informal ☑ Minor Works Fabric □ |
| Improve access to Tower | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 57 of 139

| Case No: L040/2012 | Informal 🗌 Minor Works Fabric 🗹 |
|--|---|
| Installation of roof alarm | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That the mains electric spur is installed by an approved NIC/EIC electrical | |
| Case No: L171/2013 | Informal ☐ Minor Works Fabric ☐ |
| 1. Cleaning of leaded and stained glass windows (to included removal and re-fixing of 2 x guards) | Minor Works Trees ☐ Faculty ☑ |
| 2. Repairs to 20 x cracked panes of glass3. Temporary removal, cleaning and re-leading of medieval section of glass in Window F | Recommended Not Recommended No objections |
| 4. Installation of new guards (7 in all) to windows C, N, & F | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 14/03/2014 |
| 1. A time limit of 24 months | |
| 2. That the works are recorded in the Log Book so that a record is kept of what has been done | |
| That the window grilles are of black powder coated stainless steel and shaped to fit | |

29 February 2024 Page 58 of 139

| Case No: | Informal $\;\square\;$ Minor Works Fabric $\;\square\;$ |
|---|---|
| Install three LED floodlights in the churchyard to light up the north face of the church for a few hours each evening | Minor Works Trees ☐ Faculty ✔ |
| J J | Recommended Not Recommended No objections |
| | |
| | Withdrawn ✓ |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| That an updated Electrical Condition Report is commissioned, and submitted to the DAC Secretary, after the installation | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| Replacement of cracked and fractured guttering downpipes | Minor Works Trees \Box Faculty \Box |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 59 of 139

| Ben No: | Church | |
|--|-------------------------------|---|
| 20311 | Ashby Magna, St Mary | |
| Case No: | L083/2000 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Removal of decaying plaster from walls | f decaying plaster from walls | Minor Works Trees ☐ Faculty ✔ Recommended Not Recommended No objections ☐ ☐ ☐ Withdrawn ☐ |
| | Faculty Issued? □ | |
| DAC Cert | ificate Conditions: - | Date Faculty Issued |
| 1. A time lir | mit of 12 months | |

29 February 2024 Page 60 of 139

| Case No: L087/2000 | Informal $\;\sqcup\;$ Minor Works Fabric $\;\sqcup\;$ |
|--|---|
| Installation of new heating system | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objection |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 16/07/2001 |
| 1. A time limit of 12 months | |
| Case No: L084/2000 | Informal □ Minor Works Fabric □ |
| Removal of Aumbry (Certificated 25 September 2000) | Minor Works Trees ☐ Faculty 🗹 |
| | Recommended Not Recommended No objection |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| | |
| | |

29 February 2024 Page 61 of 139

| Case No: L033/2006 | Informal 🗀 Minor Works Fabric 🗀 |
|--|--|
| Erect picket fence 1m high around 5m strip of churchyard adjoining Gilmorton Road to protect graves from sheep in the churchyard Designate the smaller area as a Garden of Remembrance - interments to be marked with flat r stones as per the Chancellor's Regulations | Willion Works Troop T doubly |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 07/07/2006 |
| 1. A time limit of 12 months Case No: L136/2006 | Informal □ Minor Works Fabric □ |
| 1. Remove existing s Nave wall plaster and re-render | Minor Works Trees Faculty |
| 2. Installation of 3-phase electricity supply | Willion Works Troop Tabaky |
| 3. Re-positioning of existing 3 heaters from s Nave wall to chancel4. Installation of 13 new ceramic heaters in Nave | Recommended Not Recommended No objections ☑ □ □ |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 22/11/2006 |
| 1. A time limit of 12 months | |
| 2. That, in the event of wall paintings being discovered, the works stop immediately and the advise of the DAC is sought | |

29 February 2024 Page 62 of 139

| Case No: L180/2007 | Informal 🖂 Minor Works Fabric 🗀 |
|---|---|
| Installation of 3 x 8' cast-iron lamps along the churchyard path to the north door | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 10/07/2008 |
| A time limit of 12 months That the PCC obtains written confirmation whether planning permission is required | |
| Case No: L057/2008 | Informal ☐ Minor Works Fabric ☑ |
| Temporary installation of CCTV camera to protect roof | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That the works are recorded in the Log Book so that a record is kept of what has been done | |
| That the PCC makes a faculty application for the permanent installation | |

29 February 2024 Page 63 of 139

| Case No: L170/2008 | Informal 🖂 Minor Works Fabric 🖳 |
|--|---|
| To make permanent the temporary installation of CCTV camera to protect roof permitted u Minor Works provision | nder the Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 06/01/2009 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L101/2009 | Informal |
| Repairs to the treads of the Tower spiral staircase | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn ✓ |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| 2. That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 64 of 139

| Case No: L086/2009 | Informal 🗌 Minor Works Fabric 🗎 |
|---|---|
| Repairs identified by the 2005 Quinquennial Inspection: - | Minor Works Trees ☐ Faculty ☑ |
| Re-pointing of external south Nave wall Removal and replacement of plasterwork on whole of Vestry internal east wall | Recommended Not Recommended No objections |
| 2. Removal and replacement of plasterwork on whole of vestry internal east wall | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That the work should be carried out at the direction of the church architect | |
| Case No: L088/2010 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| To: - | Minor Works Trees ☐ Faculty ✓ |
| Strip and re-render Vestry east wall Re-point the Nave south wall | Recommended Not Recommended No objections |
| 2. No point the Nave South Wall | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| 2. That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 3. That the mix for the mortar must be as per the architect's specification | |

29 February 2024 Page 65 of 139

| Case No: L172/2015 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| CONFIRMATORY APPLICATION for works undertaken: - | Minor Works Trees ☐ Faculty ✓ |
| Felling of large Wellingtonia Tree | Recommended Not Recommended No objection Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 23/04/2020 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric □ |
| CONFIRMATORY APPLICATION for works undertaken with Interim Faculty: - | Minor Works Trees ☐ Faculty ✓ |
| Re-covering of the North Aisle | Recommended Not Recommended No objection |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued 23/04/2020 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 66 of 139

| Case No: | Informal 🗌 Minor Works Fabric 🗹 |
|--|---|
| Repairs to the: - 1. Stonework 2. Glazing of the Tower / Belfry Window | Minor Works Trees ☐ Faculty ☐ Recommended Not Recommended No objections ✓ ☐ ☐ |
| | Withdrawn Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric □ |
| Commemorative plaque for Queen's Jubilee | Minor Works Trees ☐ Faculty ✔ Recommended Not Recommended No objections ✔ ☐ ☐ Withdrawn ☐ Faculty Issued? ✔ |
| DAC Certificate Conditions: - | Date Faculty Issued 27/06/2022 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 67 of 139

| Ben No: | Church | |
|---|---|--|
| 20304 | Ashby Parva, St Peter | |
| Case No: | L069/2002 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| 1 Repair and 2. Masonry ro 3. Plaster rep 4. Repairs to 5. Joinery rep 6. Glazing re | ne fabric including: - d decoration of rainwater goods repairs and re-pointing pair to roof o loose floor tiles in Porch pairs repairs and provision of window guard o Tower roof | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn Faculty Issued? |
| | icate Conditions: - it of 12 months | Date Faculty Issued |

29 February 2024 Page 68 of 139

| Case No: L074/2003 | Informal 🗀 Minor Works Fabric 🗀 |
|---|--|
| Installation of slate tablet on wall of north porch in memory of Mrs Maude Wilford. Plaque to be approximately 10" X 14" with lettering in gold (Mrs Wilford was a supporter, regular worshipper and be ringer for many years). | Recommended Not Recommended No objections |
| | ✓ □ □ □ Withdrawn □ □ Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| Case No: L130/2005 | Informal □ Minor Works Fabric ☑ |
| Lightning Conductor repair works | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |

29 February 2024 Page 69 of 139

| Case No: L089/2006 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| Pruning of the Tree of Heaven | Minor Works Trees ✓ Faculty □ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| Case No: L067/2007 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Electrical works: - | Minor Works Trees ☐ Faculty ✔ |
| As detailed in the Inspection Report (8 October 2004) Re-wire lighting circuits | Recommended Not Recommended No objections |
| 3. Replace lights and fittings | |
| 4. Replace heating programmer | |
| 5. Fit conduit to protect heater wiring to s side of Nave | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 19/06/2007 |
| 1. A time limit of 12 months | |
| 2. That all wiring should be as unobtrusive as possible and of an appropriate colour to | |
| blend with the background 3. That, where possible, all fixings should be made into joints, not stonework, using | |
| | |

29 February 2024 Page 70 of 139

| Case No: L099/2008 | Informal ☐ Minor Works Fabric ☑ |
|--|---|
| Repairs to tarmac paths and widening to 1m to allow access for the disabled Application of 'Smartwater' | Minor Works Trees Faculty Recommended Not Recommended No objections |
| | Withdrawn ☐ Faculty Issued? ☐ |
| 1. That details of the works are entered in the Log Book so that a record is kept of what has been done 2. That the PCC records the unique signature of the 'S,artwater' in the Log Book so that items removed illegally can be traced back to the church of origin and displays | Date Faculty Issued |
| Case No: L154/2008 | Informal □ Minor Works Fabric □ |
| Removal, and retention for spare parts, of: - a) 2 tube heaters (600W) from pews scheduled for removal by Faculty issued 7 March 2008 b) 1 tube heater (wattage unknown) from Sanctuary wall Installation of 2 Dimplex Duoheat, Duo500i, 1.4kW storage heaters: - a) North-west corner on north wall b) North wall of Sanctuary | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn |
| DAC Certificate Conditions: - | Faculty Issued? Date Faculty Issued 14/10/2008 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 71 of 139

3. That, where possible, all fixings should be made into joints, not stonework, using

| Case No: L015/2008 | Informal 🗀 Minor Works Fabric 🗀 |
|---|--|
| Re-location of the font from bell tower to rear north-west corner of church Removal and disposal of 2 pews (dated 1845) from north-west corner of church Repairs to Victorian tiled floor and lime plaster resulting from 1 & 2 | Minor Works Trees ☐ Faculty ✔ Recommended Not Recommended No objections |
| | Withdrawn ☐ Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 07/03/2008 |
| 1. A time limit of 12 months Cons No. 1 046/2008 | Informal □ Minor Works Fabric □ |
| QI Repairs comprising: - | Minor Works Trees Faculty |
| Repair and decoration of rainwater goods Masonry repairs and re-pointing Plaster repair to porch roof Joinery repairs Glazing repairs and provision of window guard Repairs to loose floor tiles | Recommended Not Recommended No objections Withdrawn Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 07/03/2008 |
| 1. A time limit of 12 months | |

29 February 2024 Page 72 of 139

| Case No: L166/2009 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|---|--|
| CONFIRMATORY APPLICATION: - | Minor Works Trees ☐ Faculty ✓ |
| Installation of new water main across the churchyard | Recommended Not Recommended No objections □ □ □ ✓ |
| | Withdrawn |
| | Faculty Issued? 🗹 |
| DAC Certificate Conditions: - | Date Faculty Issued 04/12/2009 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L081/2009 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| CONFIRMATORY APPLICATION: - 1. Crown lift and other works to: - a) 4 x Lime Trees b) 1 x Yew Tree c) 1 x Spruce Tree 2. Fell 3 x Cherry Trees | Minor Works Trees Faculty Recommended Not Recommended No objections |
| DAC Certificate Conditions: - | Date Faculty Issued 29/10/2012 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 73 of 139

| Case No: L207/2010 | Informal 🗌 Minor Works Fabric 🗹 |
|--|---|
| 1. Re-location of 4 x skirting heaters in the Sanctuary to be used under the priest and choir stalls in Chancel | Minor Works Trees $\ \Box$ Faculty $\ \Box$ |
| 2. Install 5 x Dimples 1.0KW Monterey panel heaters in Sanctuary | Recommended Not Recommended No objections |
| 3. Replacement of 17 x with 17 x Dimple T240W/T360W tube heaters under the Nave pews | |
| 4. Replacement of 2 x skirting heaters with 2 x Dimplex 1.0KW Monterey heaters in the welcome area | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L206/2010 | Informal ☐ Minor Works Fabric ☑ |
| Re-location of the electric meter etc from west wall of the Tower to north wall | Minor Works Trees \Box Faculty \Box |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 3. That the cupboard should be locked and the appropriate warning notice displayed | |

29 February 2024 Page 74 of 139

| Case No: L027/2011 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|---|--|
| Following the 2009 QI Report, repairs to the window casements and masonry comprising: 1. Repair dislodged stone above vestry door 2. Repair Porch gable 3. Repair jamb of window 10 4. Re-point window 7 5. Repair jamb of window 3 6. Repair cusped heads of windows 5,6,7 7. Repair tracery window 5 | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn Faculty Issued? |
| 8. Repairs to cusped heads and tracery of window 8 DAC Certificate Conditions: - 1. A time limit of 12 months 2. That details of the works are entered in the Log Book so that a record is kept of what has been done | Date Faculty Issued 13/04/2011 |
| Case No: L055/2012 | Informal □ Minor Works Fabric □ |
| Fell 1 Blue Cedar damaged by storm | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 75 of 139

| Case No: L071/2012 | Informal 🗌 Minor Works Fabric 🗹 |
|---|---|
| Repairs to flagpole | Minor Works Trees |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L166/2012 | Informal 🔲 Minor Works Fabric 🗹 |
| Re-decoration of the: - | Minor Works Trees ☐ Faculty ☐ |
| Bell Tower - all 3 walls to a height of approximately 3m West wall of the northwest corner of the Nave | Recommended Not Recommended No objections |
| 3. South wall of the Nave | ✓ □ |
| 4. Sanctuary (to include making good following the removal of heater) | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 76 of 139

| Case No: L167/2012 | Informal 🗌 Minor Works Fabric 🗹 |
|--|--|
| Completion of the Minor Works authorised on 29 November 2010, namely to: - 1. Replace the tube heater in each of 6 pews on the north side of the Nave with Dimplex 240 Heaters, retaining and re-using the existing metal guards 2. Replacement of the tube heater in each of 11 pews on the south side of the Nave with Dir Tube Heaters to be protected by new guards 3. Removal and disposal of the redundant protection guards from the 11 pews on the south Nave | Recommended Not Recommended No objection mplex 360w side of the Withdrawn |
| DAC Certificate Conditions: - | Faculty Issued? □ Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L069/2012 | Informal □ Minor Works Fabric □ |
| Replacement of Cross over the North Porch destroyed by storm | Minor Works Trees Faculty Recommended Not Recommended No objection |
| DAC Certificate Conditions: - | Date Faculty Issued 14/06/2012 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 77 of 139

Case No: L166/2013

- 1. To remove guards and tubular heaters from all pews (17) in the Nave
- 2. To sell guards and tubular heaters
- 3. To supply and install 1 x 3 Phase contactor and distribution to feed replacement heaters on north side of Nave
- 4. To alter circuitry in existing metal conduit to the south Nave to balance supply
- 5. To purchase: -
- a) 12 x 250W convector heaters as supplied by Electrical Heating Solutions (EHS) specification attached
- b) 22 x 500W convector heaters as supplied by Electrical Heating Solutions (EHS) specification attached
- 6. To fit: -
- a) To each of 6 pews to the north of the Nave; 2 x 250W convector heaters (as supplied by EHS) beneath the pews
- b) To each of the 11 pews to the south of the nave; 2 x 500W convector heaters (as supplied by EHS) beneath the pews

DAC Certificate Conditions: -

- 1. A time limit of 12 months
- 2. That details of the works are entered in the Log Book so that a record is kept of what has been done
- 3. If the radiant heaters are to be added later this will be subject to a further

| Informal \square M | linor Works Fabric | ✓ |
|----------------------|---------------------|---------------|
| Minor Works T | rees | lty \square |
| Recommended | Not Recommended | No objections |
| \checkmark | | |
| , | Withdrawn | |
| Facult | y Issued? \square | |

Date Faculty Issued

29 February 2024 Page 78 of 139

| Case No: L213/2013 | Informal ☐ Minor Works Fabric ☑ |
|--|---|
| To commission the fabrication of a new gold Altar Frontal To re-use portions of the existing Altar Frontal and to dispose the remainder | Minor Works Trees ☐ Faculty ☐ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That proposals to display / re-use the "preserved" portions of the Gold Altar Frontal | |
| Case No: L054/2013 | Informal ☐ Minor Works Fabric ☐ |
| 1. Felling of: - | Minor Works Trees ✓ Faculty □ |
| a) Hawthorn Tree (T9) b) Tree of Heaven (T21) | Recommended Not Recommended No objections |
| c) Horse Chestnut (T39) 2. Genral works to 2 x Hawthorn Trees (T22 & T41) | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That the PCC ensures that Harborough District Council has issued its consent | |

29 February 2024 Page 79 of 139

| Case No: L019/2014 | Informal 🗌 Minor Works Fabric 💆 |
|--|---|
| Disposal of: - | Minor Works Trees Faculty |
| 1. Red: - a) Altar Frontal | Recommended Not Recommended No objections |
| b) Burse | ✓ □ □ |
| c) Veil | |
| 2. Gold: - | Withdrawn |
| a) Burse | Withdrawii |
| b) Veil | Faculty leaved? |
| 3. Green: - | Faculty Issued? └ |
| a) Frontal | |
| b) Pulpit Fall | |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L102/2014 | Informal ☐ Minor Works Fabric ☐ |
| Installation of Window protection grills to: - | Minor Works Trees ☐ Faculty ✔ |
| 1. South window - 'Devil' window | |
| 2. Tower west window | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 19/06/2014 |
| 1. That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 2. That the window grilles are of black powder coated stainless steel and shaped to fit | |
| into any tracery of the windows and that, where possible, all fixings should be made | |

29 February 2024 Page 80 of 139

| Case No: L179/2014 | Informal $\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$ |
|--|--|
| To section fell: - 1. Cypress spp (23) | Minor Works Trees Faculty □ |
| 2. Norway Spruce (42) | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric ☑ |
| Replacement of the underlay beneath the carpet in the Nave Aisle | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 81 of 139

| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| Roof, Masonry and Rainwater goods Repairs | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 14/12/2016 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 2. That, should excavations become necessary as part of the repairs to raiwater goods, the works should be halted and the DAC Archaeological Adviser consulted | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| Crown lifting of Yew Tree | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 82 of 139

| Case No: | Informal 🗀 Minor Works Fabric 💆 |
|--|---|
| Repairs to plaster and wall coating to match existing in the following areas: - 1. Bell Tower | Minor Works Trees Faculty |
| 2. Nave | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric □ |
| Disposal of Prayer Desk | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? 🗹 |
| DAC Certificate Conditions: - | Date Faculty Issued 05/07/2016 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 83 of 139

| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|---|---|
| CONFIRMATORY APPLICATION: - | Minor Works Trees ☐ Faculty ✓ |
| To: - 1. Install a new | Recommended Not Recommended No objections ☑ □ □ |
| 2. Re-locate and shorten the of the existing Bell Tower ladder | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 04/09/2018 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric ☑ |
| Installation of Roof Alarm | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 2. That, in line with the requirement and advice of the Ecclesiastical Insurance Group, the installation and/or testing must be carried out by an electrician who is an | |

29 February 2024 Page 84 of 139

| Case No: | Informal 🗌 Minor Works Fabric 🗹 |
|---|--|
| Electrical repairs following Electrical Inspection comprising: - 1. Replacement of twin socket (by Organ) and RCBO unit in distribution board 2. Replacement of RCBO unit for Pulpit and rear sockets | Minor Works Trees Faculty Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That are undertailed Condition Report is commissioned, and submitted to the | |
| That an updated Electrical Condition Report is commissioned, and submitted to the DAC Secretary, after the installation | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| Repairs to wall coating of Tower to match existing | Minor Works Trees $\ \square$ Faculty $\ \square$ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 85 of 139

| Case No: | Informal 🗀 Minor Works Fabric 🗀 |
|---|---|
| Removal of safety hoop to the alloy safety ladder in the Tower Installation of fall-arrest system | Minor Works Trees ☐ Faculty ✔ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 06/08/2019 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| That the PCC instigates an annual regime for testing the system | |
| Case No: | Informal ☐ Minor Works Fabric ☐ |
| CONFIRMATORY APPLICATION for works undertaken with Interim Faculty: - | Minor Works Trees ☐ Faculty ✓ |
| Structural repairs to the Bell Frame | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 13/10/2021 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 86 of 139

| Case No: | Informal 🗀 Minor Works Fabric 🗀 |
|--|---|
| Place a memorial plaque to Graham John Bundock beside a memorial tree in churchyard | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| CONFIRMATORY APPLICATION for works undertaken: | Minor Works Trees ☐ Faculty ☑ |
| Planting of a Rowan Tree | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 13/01/2024 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 87 of 139

| Ben No: | Church | |
|--|--|---|
| ? | Ashby Woulds, (Local Authority) Cemetery | |
| Case No: | | Informal ☐ Minor Works Fabric ☐ |
| No application for Minor Works / Informal Advice / Formal Advice has been made | | Minor Works Trees \Box Faculty \Box |
| | | Recommended Not Recommended No objections |
| | | |
| | | Withdrawn |
| | | Faculty Issued? □ |
| DAC Cert | ificate Conditions: - | Date Faculty Issued |
| 1. A time lir | mit of 12 months | |
| | | |
| | | |

29 February 2024 Page 88 of 139

| Ben No: | Church | |
|--|---|---------------------------------|
| | Ashby-de-la-Zouch, (Local Authority) Cemetery | |
| Case No: | | Informal □ Minor Works Fabric □ |
| No application for Minor Works / Informal Advice / Formal Advice has been made | Minor Works Trees ☐ Faculty ☐ | |
| | Recommended Not Recommended No objections | |
| | | |
| | | Withdrawn |
| | | Faculty Issued? |
| DAC Cert | ificate Conditions: - | Date Faculty Issued |
| 1. A time lir | mit of 12 months | |
| | | |
| | | |

29 February 2024 Page 89 of 139

| Ben No: | Church | |
|---------------|---------------------------------|---|
| 20207 | Ashby-de-la-Zouch, Holy Trinity | |
| Case No: | L/1999 | Informal □ Minor Works Fabric □ |
| Restoration | of Sundial | Minor Works Trees ☐ Faculty ☑ |
| | | Recommended Not Recommended No objections |
| | | |
| | | Withdrawn |
| | | Faculty Issued? ✓ |
| DAC Cert | ificate Conditions: - | Date Faculty Issued 04/01/2000 |
| 1. A time lir | mit of 12 months | |

29 February 2024 Page 90 of 139

| Case No: L065/2002 | Informal 🗀 Minor Works Fabric 🗀 |
|--|---|
| Installation of new boiler into the Bell Tower | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 29/10/2002 |
| 1. A time limit of 12 months | |
| | |
| | |
| Case No: L095/2004 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Restoration of Bells | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 05/11/2004 |
| 1. A time limit of 12 months | |
| The PCC needs to provide the DAC with photographs (preferably digitally) of the tower before and after the works | |

29 February 2024 Page 91 of 139

| Case No: L166/2005 | Informal $\ \square$ Minor Works Fal | oric \square |
|--|--------------------------------------|-------------------|
| 1. Repairs to stonework | Minor Works Trees | aculty 🗹 |
| Roofing works Timber treatment | Recommended Not Recommen | ded No objections |
| 4. Repairs to iron window frame to window of Priest's Room | | |
| 5. Repairs to lightning conductor6. Repairs to south boundary wall with Manor House School (from the gate southwards)7. Repairs to the wood board coat of arms in the Hastings Chapel and chancel (6 in all) | Withdrawn | |
| | Faculty Issued? | |
| DAC Certificate Conditions: - | Date Faculty Issued | 11/08/2006 |
| 1. A time limit of 12 months | | |
| Case No: L101/2005 | Informal ☐ Minor Works Fal | oric \square |
| Removal of existing boiler flue | Minor Works Trees | aculty 🗹 |
| Installation of new boiler flue Replace one section of String Course brickwork damaged during installation of existing boiler flue | Recommended Not Recommen | ded No objections |
| 4. Plant low level holly hedging in front of the new boiler flue to render it "invisable" from ground level | | |
| | Withdrawn | |
| | Faculty Issued? [✓] | |
| DAC Certificate Conditions: - | Date Faculty Issued | 18/07/2007 |
| 1. A time limit of 12 months | | |

29 February 2024 Page 92 of 139

| Case No: L196/2006 | Informal 🗌 Minor Works Fabric 🗹 |
|---|--|
| Works to the Organ comprising of: - 1. Cleaning of all pipes, re-fitting, individual regulating and fine tuning following the cleaning proces: 2. Construction of a box to be fitted at the back of the swell-box for access to tune the mixture and prevent shading of the pipes 3. Fitting a new flexible truck to the bellows | |
| 4. Full cleaning of console keys, pedals, with coverboards fitted above and contact assemblies5. Fitting hardboard about trumpet and clarion pipes | Withdrawn ☐ Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 02/01/2007 |
| 1. A time limit of 12 months Case No: L174/2009 | Informal □ Minor Works Fabric □ |
| Replacement of gas-fired boilers in the existing boiler house | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objection |
| | ✓ □ □ □ Withdrawn □ |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 04/12/2009 |
| 1. A time limit of 12 months 2. That details of the works are entered in the Log Book so that a record is kept of what has been done 3. That where possible all fivings should be made into initial part standards with the production. | |
| 3. That, where possible, all fixings should be made into joints, not stonework, using | |

29 February 2024 Page 93 of 139

| Case No: L209/2010 | Informal 🗀 Minor Works Fabric 🗀 |
|--|---|
| Repairs to the Transept parapet | Minor Works Trees ☐ Faculty 🗹 |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 05/11/2010 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L147/2011 | Informal □ Minor Works Fabric □ |
| 1. Roof repairs | Minor Works Trees ☐ Faculty ✔ |
| Window work Masonry repair | Recommended Not Recommended No objections |
| 4. Internal work | ✓ □ |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 03/11/2011 |
| 1. A time limit of 12 months | |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 94 of 139

| Case No: L024/2013 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| Felling of: - a) Beech (T15) b) Silver Birch (T24) c) Cherry (T28) Crown lifting of Beech (T2) General works to 9 other trees | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn |
| DAC Certificate Conditions: - | ☐ Faculty Issued? ☐ Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L017/2013 | Informal ☐ Minor Works Fabric ☐ |
| In the Hastings Chapel, installation of a fine rubbed Nabresina Limestone flat (2" thick x 1'8" wide x 1'3 deep) tablet, under the existing memorial to the 16th Earl of Huntingdon, to Lady Moorea Black | Minor Works Trees Faculty Recommended Not Recommended No objections ✓ □ □ Withdrawn □ Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 24/07/2013 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That, in the fourth line of the plaque, "Of" should be amended to "of" | |

29 February 2024 Page 95 of 139

| Case No: L170/2015 | Informal ☐ Minor Works Fabric ☐ |
|--|---|
| 1. Introduction of signage & learning materials | Minor Works Trees ☐ Faculty ☑ |
| 2. Introduction of digital technology 'visbox' | , |
| 3. Installation of Welcome Desk | Recommended Not Recommended No objections |
| 4. Additional speakers to enhance the Sound System | |
| 5. Re-location of Noticeboard to north wall | With drawn |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 28/07/2017 |
| That details of the works are entered in the Log Book so that a record is kept of | • |
| what has been done | |
| 2. That, in line with the requirement and advice of the Ecclesiastical Insurance Group, | |
| the installation and/or testing must be carried out by an electrician who is an | |
| Case No: L178/2015 | Informal □ Minor Works Fabric □ |
| Re-ordering of the Churchyard comprising: - | Minor Works Trees ☐ Faculty 🔽 |
| 01. Refurbishment of gates and pillars at northwestern entrance | Willor Works frees Faculty |
| 02. Works to remove various trip hazards associated with kerbs and memorials | Recommended Not Recommended No objections |
| 03. Re-creation of flower beds | |
| 04. Re-location of headstones currently against the south and west walls of the churchyard west of the | |
| Tower | Withdrawn 🗸 |
| 05. Removal of the path and Bench west of the Tower | |
| 06. Creation of Outdoor Learning Space 07. Creation of path to and enlargment of hard-standing around the War Memorial | Faculty Issued? |
| 08. Upgrading of lighting in the churchyard | • |
| | |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |

29 February 2024 Page 96 of 139

2. That details of the works are entered in the Log Book so that a record is kept of what has been done

| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|--|
| Dig a trench to lay: - 1. Water | Minor Works Trees ☐ Faculty ✓ Recommended Not Recommended No objections |
| 2. Electricity services | ✓ □ □ |
| | Withdrawn ☐ Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 02/08/2016 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That no works shall take place until the PCC, after consultation with the Diocesan Archaeological Adviser, has secured the implementation of a programme of | |
| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Planting of Trees: - 1. T6 –T10 - Suitable replacements along the boundary as part of a landscape scheme 2. T20 - Holly - plant replacement further from the wall 3. T27 - Maple - plant a more suitable replacement | Minor Works Trees |
| | Withdrawn |
| DAC Certificate Conditions: - | Faculty Issued? □ Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | Date I douby 199ded |

29 February 2024 Page 97 of 139

| Case | No: |
|------|-----|
| | |

| Felling of Trees: - | |
|---|--|
| Γ3 Fell and stump treat the adjacent small Ash and Sycamore natural regen | |
| Γ6 – T10 Fell | |
| Γ12 Hornbeam | |
| T14 Cherry sucker | |
| Γ16 Ash | |
| Γ20 Holly | |
| T27 Maple | |

DAC Certificate Conditions: -

- 1. That details of the works are entered in the Log Book so that a record is kept of what has been done
- 2. That the work, and timing, should minimise disturbance to birds and bats potentially in the area

| Informal $\ \square$ Minor Works Fabric | |
|---|---------------|
| Minor Works Trees Facu | Ity \square |
| Recommended Not Recommended | No objections |
| | |
| Withdrawn | |
| Faculty Issued? \Box | |
| Date Faculty Issued | |

29 February 2024 Page 98 of 139

Case No:

Works to Trees comprising: -

T1 Birch: Crown lift to 2m. (3m. east side). Clean out.

T2 Beech: Crown lift to 3m. Clear building by 2m. Thin the crown by 20%.

T3 Lightly trim following re-assessment after adjacent felling

T4 Lightly trim following re-assessment after adjacent felling

T5 Horse chestnut: Clean out and crown lift

T13 Oak: Crown lift by removal of one low branch on south side, two on north side to improve view of the church from Leicester Road and secondary branches to provide 4m. clearance. Prune out dead branches and central epicormics.

T17 Beech: Prune out dead branches. Thin out the lower third of canopy by removal of internal secondary branches and weaker growth. Lightly crown lift over the footway,towards T14 and T18 T18 Cut-leaf beech: Crown lift lightly over highway by removal of secondary branches and one branch on north side extending towards T19

T19 Cherry: Clean out

T21 Oak: Thin the crown as T17. Crown lift by removal of one branch on west side near light column 3

T22 Weeping cherry: Formative prune

T25 Oak:Clean out and crown lift

DAC Certificate Conditions: -

- 1. That details of the works are entered in the Log Book so that a record is kept of what has been done
- 2. That the work, and timing, should minimise disturbance to birds and bats potentially in the area

| Informal \square N | linor Works F | abric | ✓ |
|----------------------|---------------|-------|---------------|
| Minor Works T | rees | Facu | lty \square |
| Recommended | Not Recomm | ended | No objections |
| ✓ | | | |
| , | Withdrawn [| | |
| Facult | ty Issued? |] | |

Date Faculty Issued

29 February 2024 Page 99 of 139

| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| Improve ground drainage Tower floodlighting | Minor Works Trees ☐ Faculty ✓ |
| 3. Remove slab churchyard path | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 18/10/2017 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 2. That upon completion of the project, a report on the archaeological investigations | |
| be forwarded to the Diocesan Archaeological Advisor and DAC Secretary | |
| | |
| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Installation of improved interior lighting scheme - phase one | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 2. That, in line with the requirement and advice of the Ecclesiastical Insurance Group, | |
| the installation and/or testing must be carried out by an electrician who is an | |

29 February 2024 Page 100 of 139

| Case No: | Informal $\;\square\;$ Minor Works Fabric $\;\square\;$ | |
|--|---|------|
| Replacement of external Noticeboards | Minor Works Trees ☐ Faculty ✓ | |
| | Recommended Not Recommended No object | ions |
| | | |
| | Withdrawn | |
| | Faculty Issued? 🗹 | |
| DAC Certificate Conditions: - | Date Faculty Issued 23/08/2017 | |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That the post holes be dug by hand That Human Remains should be expected when excavating within a churchyard. | | |
| Case No: | Informal ☐ Minor Works Fabric ☐ | |
| Upgrading of the Lighting System - Phase 1 | Minor Works Trees ☐ Faculty ✓ | |
| | Recommended Not Recommended No object | ions |
| | | |
| | Withdrawn | |
| | Faculty Issued? 🗹 | |
| DAC Certificate Conditions: - | Date Faculty Issued 07/12/2017 | |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | | |
| 2. That, in line with the requirement and advice of the Ecclesiastical Insurance Group, the installation and/or testing must be carried out by an electrician who is an | | |

29 February 2024 Page 101 of 139

| Case No: | Informal $\;\square\;$ Minor Works Fabric $\;\square\;$ |
|--|---|
| Undertaking of Ground-pentrating radar to establish the existence of Vaults within the church | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn ✓ |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Installation of an information / orientation board in the churchyard | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 13/06/2019 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| That Human Remains should be expected when excavating within a churchyard. Any remains should be recovered, treated in a respectful manner and boxed or | |

29 February 2024 Page 102 of 139

| Case No: | Informal 🗀 Minor Works Fabric 🗀 |
|--|---|
| CONFIRMATORY APPLICATION for works undertaken: - | Minor Works Trees ☐ Faculty ✓ |
| Repairs to the Electrical System | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued 05/06/2019 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 2. That an updated Electrical Condition Report is commissioned, and submitted to the DAC Secretary, after the installation | |
| Case No: | Informal □ Minor Works Fabric □ |
| Adaptation of Choir Stalls to make them moveable | Minor Works Trees ☐ Faculty ☑ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 16/05/2019 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 103 of 139

| Case No: | Informal 🖂 Minor Works Fabric 🗀 |
|--|---|
| Installation of semi-permanent displays within the church | Minor Works Trees ☐ Faculty ☑ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 05/06/2019 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric ☑ |
| Repair to damaged and weakened floor boards | Minor Works Trees ☐ Faculty ☐ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 104 of 139

| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|---|---|
| Churchyard re-ordering comprising works to: - 1. Borders | Minor Works Trees ☐ Faculty ✓ |
| 2. Paths | Recommended Not Recommended No objections |
| 3. Kerbs 4. Lights | |
| 5. Bins6. Benches | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 26/04/2019 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That Human Remains should be expected when excavating within a churchyard. | |
| Any remains should be recovered, treated in a respectful manner and boxed or | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| Replacement of failed electrical cabling to Organ circuit | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| The Electrical Contractor needs to allow for RCBO protection on any new or existing circuits | |

29 February 2024 Page 105 of 139

| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|---|--|
| Removal of: - 1. 2 x tapestry kneeling rails from the Hastings Chapel 2. Hastings Tomb Kneeler from the Hastings Chapel 3. Carpet, underlay and carpet rails from the High Altar 4. Carpet at Altar rail in the Lady Chapel 5. Carpet in St Michael's Chapel 6. Batik picture in the South Aisle 7. Flame of Ashby picture in the South Aisle 8. Various modern banners – Fruit of Spirit, Lent, Come Let us Sing, etc from the Pillars | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn Faculty Issued? |
| DAC Certificate Conditions: - 1. That details of the works are entered in the Log Book so that a record is kept of what has been done | Date Faculty Issued 16/03/2020 |
| Case No: | Informal □ Minor Works Fabric ☑ |
| Remove asbestos from: - 1. Around heating pipes beneath the Organ 2. Boiler Room floor and pipes 3. Distribution Board | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn Faculty Issued? |
| DAC Certificate Conditions: - 1. That details of the works are entered in the Log Book so that a record is kept of what has been done | Date Faculty Issued |

29 February 2024 Page 106 of 139

| Case No: | Informal 🗌 Minor Works Fabric 💆 |
|--|---|
| Replacement electrical distribution board | Minor Works Trees \Box Faculty \Box |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 2. That an updated Electrical Condition Report is commissioned, and submitted to the DAC Secretary, after the installation | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| To install a replacement intruder alarm system | Minor Works Trees ☐ Faculty ☐ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1.That details of the works are entered in the Log Book; | |
| 2.That an updated Electrical Condition Report is commissioned and submitted to the DAC Secretary after the installation; | |
| 3. That, in line with the requirement and advice of the Ecclesiastical Insurance Group, | |

29 February 2024 Page 107 of 139

| Case No: | Informal 🗀 Minor Works Fabric 💆 |
|--|---|
| Repair and refurbish the churchyard gates | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric □ |
| Introduction of a plaque in memory of Canon John Edward Bowers | Minor Works Trees ☐ Faculty 🗹 |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 108 of 139

| Ben No: | Church | |
|---------------|---|--|
| 20207 | Ashby-de-la-Zouch, St Helen | |
| Case No: | L096/2002 | Informal ☑ Minor Works Fabric ☐ |
| To remove | Pews from the balcony area to provide storage faciliities | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn Faculty Issued? |
| DAC Cert | ificate Conditions: - | Date Faculty Issued |
| 1. A time lir | mit of 12 months | |

29 February 2024 Page 109 of 139

| Case No: L006/2003 | Informal 🖂 Minor Works Fabric 🖳 |
|---|---|
| 1. Replacement of Nave ceiling | Minor Works Trees ☐ Faculty ☑ |
| 2. Re-decoration of Nave, Chancel and entrance Porch | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| Case No: L078/2006 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Provision of replacement access ramp to West Door | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 06/09/2006 |
| A time limit of 12 months That the handrails extend beyond the ramps to comply with the appropriate regulations | |

29 February 2024 Page 110 of 139

| Case No: L114/2006 | Informal 🗌 Minor Works Fabric 🗹 |
|--|--|
| Repairs to the roof of the: - 1. Nave | Minor Works Trees Faculty |
| 2. Chancel3. Vestryas identified in the Quinquennial Report, September 2003 | Recommended Not Recommended No objections |
| | Withdrawn |
| DAC Certificate Conditions: - | Faculty Issued? |
| A time limit of 12 months That the areas to be re-pointed and the mortar mix to be used are agreed by the Church Architect before the works commence | |
| Case No: L011/2008 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Electrical works comprising the installation of new: - 1. Power supply to PA desk and new sockets on 2 new circuits 2. Sockets: - a) Twin sockets underneath both front pews b) Twin sockets within sound desk cabinet c) Single socket on beam to balcony at high level d) Single socket near sound desk for lap top computer e) Single socket above pillar next to font at high level | Minor Works Trees Faculty Recommended Not Recommended No objections ✓ □ □ Withdrawn □ Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 12/03/2008 |
| A time limit of 12 months That the PCC should use recessed floor sockets with safety covers | |

29 February 2024 Page 111 of 139

| Case No: L003/2008 | Informal $\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$ |
|---|--|
| 1. Creation of additional Garden of Remembrance (6m x 5m) to be marked out by artifiand hardwood posts with linking chains | Willion Works Troop T douby |
| 2. Installation of: - | Recommended Not Recommended No objection |
| a) Raised plinth 200mm high in south-east corner for floral tributes and flowers in va b) Hardwood bench to east side of the area in memory of John Hodges | ases $lacks$ |
| c) Plaque set in the ground to indicate Garden of Remembrance | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 12/03/2008 |
| A time limit of 12 months That the setts should be of natural stone | |
| Case No: L042/2008 | Informal \Box Minor Works Fabric \Box |
| Provision of CCTV system and associated security measures | Minor Works Trees ☐ Faculty ✔ |
| | Recommended Not Recommended No objection |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 16/06/2008 |
| 1. A time limit of 12 months | 7 |
| That, where possible, all fixings should be made into joints, not stonework, using stainless steel or non-ferrous screws in fibre plugs | |

29 February 2024 Page 112 of 139

| Case No: L041/2008 | Informal 🗀 Minor Works Fabric 💆 |
|--|--|
| Removal of asbestos: - 1. Detached boiler house | Minor Works Trees Faculty |
| 2. Heating pipe insultaltion under the Organ | Recommended Not Recommended No objections |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months Case No: L030/2009 | Informal □ Minor Works Fabric □ |
| Installation of new gas supply | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 04/04/2009 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 113 of 139

Case No: L148/2012

- 01. Removal, inspection and replacement of leaking lead gutter over South Aisle and minor remedial work to gutter over east end of the Aisle
- 02. Installation of new cast iron RWP from new outlet in parapet wall
- 03. Drainage work to include new connection into existing surface water drain from new RWP and new french drain and catch pit into existing surface water system to rear of church
- 04. Raising of parapets and gables by approx 150mm to improve resilience to water penetration from gutters
- 05. Removal of stone retaining wall/ railings and associated shrubs/ bushes to rear of church
- 06. Re-decoration of window frames and tower louvers
- 07. Remedial work to lead to tower roof
- 08. Lime pointing to high level stone work
- 09. Installation of new lead flashings and soakers to roof abutments with gables and re-slating as required to match
- 10. Landscaping of land to rear of church to allow ease of maintenance.

DAC Certificate Conditions: -

- 1. A time limit of 12 months
- 2. That details of the works are entered in the Log Book so that a record is kept of what has been done
- 3. That no works shall take place until the PCC, after consultation with the Diocesan

| Informal ☑ Minor Works Fabric ☐ | | |
|---------------------------------|---------------------|----------------|
| Minor Works T | rees | ılty \square |
| Recommended | Not Recommended | No objections |
| ✓ | | |
| Withdrawn | | |
| Facult | y Issued? \square | |

Date Faculty Issued

29 February 2024 Page 114 of 139

| Case No: L043/2013 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|---|
| Lopping of Yew Tree overhanging numbers 3 and 4 Kirkland Close | Minor Works Trees ✓ Faculty □ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L050/2013 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Works to the trees comprising: - | Minor Works Trees ✓ Faculty □ |
| 1. T12 - Remaining stump - Fell 2. T18 - Common Holly - Fell | Recommended Not Recommended No objections |
| 3. T10 & T13 - General Works | |
| 4. T16 - Common Yew - Removal of lower limbs | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| 2. That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 115 of 139

| Case No: L044/2015 | Informal $\;\sqcup\;$ Minor Works Fabric $\;\sqsubseteq\;$ |
|---|--|
| Repairs to: - 1. Roof | Minor Works Trees ☐ Faculty ☑ |
| 2. Rainwater Goods | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 23/05/2017 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That the Church Architect must agree the matches of re used slates. | |
| 2. That the Church Architect must agree the matches of re-used slates3. That any plumbers marks found on existing lead should be photographed, | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| Repair of damaged lime plaster in Nave | Minor Works Trees ☐ Faculty ☐ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| 2. That, in the event of wall paintings being discovered, the works stop immediately and the advise of the DAC is sought | |

29 February 2024 Page 116 of 139

| Case No: | Informal 🗌 Minor Works Fabric 💆 |
|---|---|
| Re-decoration of Nave | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? \square |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| That the contractors should be aware of the possibility of traces of historic wall paintingsbeing found in the course of the works. In the event of finding such material | |
| Case No: | Informal ☐ Minor Works Fabric ☐ |
| To make permanent the installation of the | Minor Works Trees ☐ Faculty ☑ |
| 'ex-demonstration Allen GX235i digital organ and four channels of Allen HR-200 external speakers wit switching included | h Recommended Not Recommended No objections |
| introduced under TMRO licence | |
| | Withdrawn |
| | lacksquare Faculty Issued? $lacksquare$ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 117 of 139

| Ben No: | Church | |
|---------------|---------------------------|---|
| 20403 | Aston Flamville, St Peter | |
| Case No: | L/1999 | Informal ☐ Minor Works Fabric ☐ |
| Installation | of new Lychgate | Minor Works Trees ☐ Faculty ☑ |
| | | Recommended Not Recommended No objections |
| | | |
| | | Withdrawn |
| | | Faculty Issued? ✓ |
| DAC Cert | ificate Conditions: - | Date Faculty Issued 04/01/2000 |
| 1. A time lii | mit of 12 months | |

29 February 2024 Page 118 of 139

| Case No: L160/2006 | Informal $\;\square\;$ Minor Works Fabric $\;\square\;$ |
|---|---|
| QI Repairs: - 1. Rainwater goods 2. Masonry repairs 3. Door ironwork 4. Glazing | Minor Works Trees ☐ Faculty ✔ Recommended Not Recommended No objections ☐ ☐ |
| 5. Flooring 6. Plasterwork 7. Window guards | Withdrawn ☐ Faculty Issued? ✓ |
| 1. A time limit of 12 months 2. That the Chancellor considers granting a two-year faculty to allow the PCC to phase the works and raise the necessary funds | Date Faculty Issued 22/12/2006 |
| Case No: L063/2009 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Removal and disposal of the existing pipe organ Installation of digital organ from Burbage, St Catherine | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 29/05/2009 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 119 of 139

| Case No: L156/2010 | Informal 🗹 Minor Works Fabric 🗀 |
|---|---|
| Creation of Garden of Remembrance | Minor Works Trees $\ \square$ Faculty $\ \square$ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That the PCC submits details of the Book of the Remembrance to be installed in | |
| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Re-laying of existing pathways | Minor Works Trees ☐ Faculty ☑ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 05/04/2017 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| That no works shall take place until the PCC, after consultation with the Diocesan Archaeological Adviser, has secured the implementation of a programme of | |

29 February 2024 Page 120 of 139

| Case No: | Informal $\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$ |
|--|--|
| Installation of: - 1. Accessible WC | Minor Works Trees ☐ Faculty ✓ |
| 2. Servery | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 121 of 139

| Ben No: | Church | |
|---------------|---|---|
| 10122 | Aylestone Park, Church of the Nativity | |
| Case No: | | Informal ☐ Minor Works Fabric ☐ |
| No Faculty | / Informal Advice / Minor Works application has been made | Minor Works Trees Faculty |
| | | Recommended Not Recommended No objections |
| | | |
| | | Withdrawn |
| | | Faculty Issued? |
| DAC Cert | ificate Conditions: - | Date Faculty Issued |
| 1. A time lir | mit of 12 months | |

29 February 2024 Page 122 of 139

| Ben No: | Church | |
|-------------|--|--|
| 10114 | Aylestone, St Andrew | |
| Case No: | L/1999 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Re-ordering | g of Chancel area | Minor Works Trees Faculty Recommended Not Recommended No objection □ □ □ Withdrawn □ Faculty Issued? ✓ |
| | ificate Conditions: - | Date Faculty Issued |
| | ificate Conditions: - mit of 12 months | Faculty Issued? ✓ |

29 February 2024 Page 123 of 139

| Case No: L153/2001 & L001a/2002 | Informal 🖂 Minor Works Fabric 🖳 |
|--|--|
| Removal of Altar in South Aisle (confirmation of temporary permission granted by the Archdeacon of Leicester in July 2001) and other alterations to the South Aisle and North Aisle including: - a) Removal of pews b) Re-siting of reredos panel c) Re-location of altar rails d) Extension of nave platform e) Re-location of font Installation of new noticeboard | Recommended Not Recommended No objections Withdrawn |
| DAC Certificate Conditions: - | ☐ Faculty Issued? ☐ Date Faculty Issued |
| 1. A time limit of 12 months | Date I deally located |
| Case No: L066/2002 | Informal \square Minor Works Fabric \square |
| Conversion of Clock from manual to automatic winding | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |

29 February 2024 Page 124 of 139

| Case No: L001b/2002 | Informal $\ \ \Box$ Minor Works Fabric $\ \ \Box$ |
|--|---|
| Installation of Votive Candle Stand | Minor Works Trees ☐ Faculty 🗹 |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. A time limit of 12 months | |
| Case No: L075/2004 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| 1. Erection of an extension to the rear of the church to provide meeting room and kitchenette area | Minor Works Trees ☐ Faculty 🗹 |
| 2. Re-ordering of interior of church to provide toilet accommodation in the Choir Vestry, additional storage and refurbishment of Tower area | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued 04/11/2004 |
| 1. A time limit of 12 months | |
| Particular attention needs to be paid to the detailing of the windows and parapet | |

29 February 2024 Page 125 of 139

| Case No: L151/2006 | Informal 🗀 Minor Works Fabric 🗀 |
|--|---|
| Stonework repairs and re-pointing to N & S Aisles, Chancel, Clergy Vestry, Tower, Nave Minor roof repairs to copper roofs | Minor Works Trees ☐ Faculty ✓ |
| 3. Glazing repairs to Nave clerestory windows | Recommended Not Recommended No objections |
| 4. Installation of replacement stainless steel guards to the east window of the North Aisle | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 16/11/2006 |
| A time limit of 12 months That the work should be carried out at the direction of the church architect That the DAC must be consulted on any required variations in the specification of the works | |
| Case No: L163/2008 | Informal □ Minor Works Fabric ☑ |
| On the Vestry roof: - | Minor Works Trees Faculty |
| Replacement of the lead flashings with Ubiflex Waterproof Flashing | Recommended Not Recommended No objections |
| | ✓ □ □ |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 126 of 139

| Case No: L160/2009 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|--|
| Work to 11 Trees comprising: - 1. Fell 1 x Cupressus Tree (number 32) 2. Remedial works to 10 Trees (numbers 1, 2, 3, 5, 6, 11, 15, and 18) | Minor Works Trees Faculty ☐ Recommended Not Recommended No objections |
| | Withdrawn Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L094b/2010 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Construction of internal ramp in South Porch Alterations to beginn evertors. | Minor Works Trees ☐ Faculty ✔ |
| Alterations to heating system Refurbishment of wood block flooring | Recommended Not Recommended No objections |
| 4. Introduction of cupboards and display panels at west end of South Aisle | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That the battens for the wall plate should be of treated softwood | |
| ' | |

29 February 2024 Page 127 of 139

| Case No: L071/2011 | Informal 🗌 Minor Works Fabric 🗹 |
|---|---|
| Replacement of existing: - 1. Par 38 light fittings with 150w Metal halide discreet light fittings in black (11 approx) | Minor Works Trees Faculty |
| Architectural and general room lighting | Recommended Not Recommended No objections |
| | Withdrawn ☐ Faculty Issued? ☐ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done That, where possible, all fixings should be made into joints, not stonework, using | |
| Case No: L087/2013 | Informal ☐ Minor Works Fabric ☐ |
| Repairs to the Bells | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 03/12/2013 |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 128 of 139

| Case No: L150/2014 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|---|--|
| In the North Aisle: - 1. Removal of 3 Pews to create a small Children's Area 2. Make good woodwork 3. Installation of soft flooring | Minor Works Trees ☐ Faculty ✔ Recommended Not Recommended No objections |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 19/12/2014 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L065/2014 | Informal □ Minor Works Fabric ☑ |
| Introduction of a Yamaha C1 Baby Grand Piano to the Chancel on long-term loan | Minor Works Trees Faculty Recommended Not Recommended No objections Withdrawn Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 129 of 139

| Case No: L241/2014 | Informal 🗀 Minor Works Fabric 🗀 |
|---|---|
| CONFIRMATORY APPLICATION for works undertaken: - | Minor Works Trees ☐ Faculty ✓ |
| Removal of 2 x existing cast iron Boilers & associated flues Installation of 2 x Worcester GB 162 65kW Gas condensing Boilers and associated venting Installation of new Heating Tank at high level in the Vestry | Recommended Not Recommended No objections □ □ □ ✓ |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 11/05/2015 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L228/2015 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Installation of CCTV System | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | Withdrawn ✓ |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| A time limit of 12 months That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 130 of 139

| Case No: L131/2015 | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|--|--|
| CONFIRMATORY APPLICATION for works undertaken: - | Minor Works Trees ☐ Faculty ✓ |
| Replacement of enclosure for commercial gas meter | Recommended Not Recommended No objections |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 11/08/2015 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: L227/2015 | Informal □ Minor Works Fabric □ |
| CONFIRMATORY APPLICATION for works undertaken: - | Minor Works Trees ☐ Faculty ✔ |
| Repairs to the roof | Recommended Not Recommended No objections Withdrawn |
| | Faculty Issued? 🗹 |
| DAC Certificate Conditions: - | Date Faculty Issued 04/04/2016 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 131 of 139

| Case No: L159/2015 | Informal $\ \ \Box$ Minor Works Fabric $\ \ \Box$ |
|---|---|
| CONFIRMATORY APPLICATION for works undertaken: - | Minor Works Trees ☐ Faculty ✓ |
| Installation of an Alarm System | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 28/09/2015 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal □ Minor Works Fabric ☑ |
| 1. Removal and disposal of debris which has fallen from the church spire and caused damage to the copper roof | Minor Works Trees \qed Faculty \qed |
| 2. Repairs to the rear copper roof where it is leaking into the church by a solder patch. | Recommended Not Recommended No objections |
| 3. Re-point rear the missing mortar to the lead step flashings adjoining the copper roof to the spire which could lead to further water ingress | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of | |
| what has been done 2. That the flashings to be pointed with lime mortar | |
| | |

29 February 2024 Page 132 of 139

| Case No: | informai □ Minor Works Fabric ♥ |
|--|---|
| Works to the Electrical System comprising: - | Minor Works Trees \Box Faculty \Box |
| Replacement of main distribution Board Removal of incorrect PME connection | Recommended Not Recommended No objections |
| 3. Replacement & re-wiring of switch bank and installation of earth bonds 4. Re-wire light & socket in Belfry | |
| 5. Re-locate emergency light over stairs6. Extend ring main up from ground floor removing fault on ground floor neutral | Withdrawn |
| 7. Put RCD at the mains end of Hager Board to protect it 8. Put banjo on main feed at mains end, strapping the armouring | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That the PCC commissions an updated Electrical Condition Report Certificate, a copy of which is to be submitted to the DAC Secretary, after the works | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| Re-location of Thermostat | Minor Works Trees |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. That details of the works are entered in the Log Book so that a record is kept of | |

29 February 2024 Page 133 of 139

2. That all wiring should be as unobtrusive as possible and of an appropriate colour to blend with the background and to be "FP200" cable or similar approved

| Case No: | Informal 🗀 Minor Works Fabric 🗀 |
|---|---|
| Installation of two sets of mesh window guards to: - 1. Two windows in the North Aisle | Minor Works Trees ☐ Faculty ✔ |
| 2. One set to the north Chancel | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 18/10/2017 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That the window grilles are of black powder coated stainless steel and shaped to fit | |
| into any tracery of the windows and that, where possible, all fixings should be made | |
| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Restoration works to the Pipe Organ | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 03/05/2019 |
| 1. That this Licence supercedes the Licence issued on 21 July 2016 2. That details of the works are entered in the Log Book so that a record is kept of what has been done 2. The trip 200 being 6 and 100 b | |
| 3. That the PCC brings forward, as soon as possible, a Faculty application for | |

29 February 2024 Page 134 of 139

| Case No: | Informal 🖂 Minor Works Fabric 🖯 |
|---|---|
| General tree maintenance to include: - 1. Deadwood removal from crowns of all boundary trees within the graveyard area opposite to the main | Minor Works Trees Faculty □ |
| church 2. T38 - mature lime - adjacent Narrow Lane, requires a crown lift (removal of low branches on the public side of the boundary line) to a height of 5m above ground level | Recommended Not Recommended No objections |
| | Withdrawn ☐ Faculty Issued? ☐ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| 1. That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| Repairs to the roofs of the: - 1. Chancel | Minor Works Trees \Box Faculty \Box |
| 2. Boiler House | Recommended Not Recommended No objections |
| 3. Cornerstone | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |

29 February 2024 Page 135 of 139

| Case No: | Informal 🗌 Minor Works Fabric 🗎 |
|--|---|
| Installation of external CCTV | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued 13/09/2018 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That an updated Electrical Condition Report is commissioned, and submitted to the DAC Secretary, after the installation | |
| Case No: | Informal □ Minor Works Fabric ☑ |
| Like-for-like replacement of Gudgeon in Treble Bell | Minor Works Trees \Box Faculty \Box |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? □ |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 136 of 139

| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
|---|---|
| Installation of polycarbonate window protection to the North Aisle | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 24/07/2018 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| That, where possible, all fixings should be made into joints, not stonework, using stainless steel or non-ferrous screws in fibre plugs | |
| Case No: | Informal ☐ Minor Works Fabric ☑ |
| Replacement of crown staples | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 137 of 139

| Case No: | Informal 🗀 Minor Works Fabric 💆 |
|--|---|
| Re- carpeting of four wooden choir kneelers: - 1. Three at 116" x 7.5" | Minor Works Trees Faculty |
| 2. One at 38" x 7.5" | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal $\ \square$ Minor Works Fabric $\ \square$ |
| Tree Management works | Minor Works Trees ✓ Faculty □ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| | |

29 February 2024 Page 138 of 139

| Case No: | Informal 🗌 Minor Works Fabric 🗹 |
|--|---|
| Repairs to roof identified in Quinquennial report | Minor Works Trees Faculty |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? |
| DAC Certificate Conditions: - | Date Faculty Issued |
| That details of the works are entered in the Log Book so that a record is kept of what has been done | |
| Case No: | Informal \Box Minor Works Fabric \Box |
| Installation of two handrails on Nave Step | Minor Works Trees ☐ Faculty ✓ |
| | Recommended Not Recommended No objections |
| | |
| | Withdrawn |
| | Faculty Issued? ✓ |
| DAC Certificate Conditions: - | Date Faculty Issued 14/11/2023 |
| That details of the works are entered in the Log Book so that a record is kept of what has been done That the handrail should be secured to the joists underneath the platform extending the Chancel | |

29 February 2024 Page 139 of 139